Department of Transport

Transport Canada Transports Canada



This approval is issued to:	Number:	PDA24-6	
Marsh Brothers Aviation Inc.	Issue No.:	1	
3225 Mainway	Approval Date:	May 03, 2024	
Burlington, Ontario Canada L7M 1A6	Issue Date:	May 03, 2024	
Responsible Office:	Prairie and Northern		
eronautical Product Type or Model: Textron Aviation Inc. Bonanza: 35, 35R, A35, B35, C35, D35, E35, F35, G3		935, E35, F35, G35.	
	Bonanza: 35-33, 35-A33, 35-B33, 35-C33, 35-C33A, 36, A36, A36TC, B36TC, E33, E33A, E33C, F33, F33A, F33C, G33, H35, J35, K35, M35, N35, P35, S35, V35, V35A, V35B.		
	Bonanza: G36.		
	Travel Air/ Baron: 56TC, 58, 58A, 95, 95-55, 95-A55, 95-C55, 95-C55A, 95-C55A, A56TC, B95, B95A, D55, D55A, D95A, E95. Baron: G58. Turbocharged Baron: 58TC, 58TCA.		
Canadian Type Certificate or Equivalent:	<ul> <li>FAA TCDS A-777 (35, 35R, A35, B35, C35, D35, E35, F35, G35)</li> <li>FAA TCDS 3A15 (35-33, 35-A33, 35-B33, 35-C33, 35-C33A, 36, A36, A36TC, B36TC, E33, E33A, E33C, F33, F33A, F33C, G33, H35, J35, K35, M35, N35, P35, S35, V35, V35A, V35B)</li> <li>A-245 (G36)</li> <li>FAA TCDS 3A16 (56TC, 58, 58A, 95, 95-55, 95-A55, 95-C55, 95-C55A, A56TC, B95, B95A, D55, D55A, D95A, E95)</li> <li>A-259 (G58)</li> <li>EAA TCDS A23CE (58TC, 58TC A)</li> </ul>		
Devile convert Devil	FAA TCDS A23CE (58TC, 58TCA)		
Replacement Part:	Cabin Door Bushing		

- See Continuation sheet -

Conditions: The installation of the approved part is to be limited only to the type / model of aeronautical product(s) listed above.

DocuSigned by:

3499A33FD63D42E... Loy Y. Liew For Minister of Transport





NOTE: THIS ADDENDUM SHALL REMAIN PART OF THE CERTIFICATE REFERRED TO THEREIN.

## Installation/Operating Data, Required Equipment and Limitations:

Manufacturing of the replacement Cabin Door Bushing must be in accordance with Transport Canada Civil Aviation (TCCA) approved Marsh Brothers Aviation (MBA) Master Data List ML-M23001-1; Revision NC dated 16 Apr 2024 or later TCCA approved revision.

Replacement parts are to be installed, inspected, and maintained in accordance with the applicable maintenance manuals appropriate to the aircraft listed above. Replacement parts introduce no new limitations or maintenance requirements.

Original OEM P/N	MBA P/N	Part Description	
35-400009	MPA 02 10007 1	Pushing	
35-400009-BSC	MBA-03-10007-1	Bushing	

## ELIGIBILITY LIST

– End –