

CESSNA FIBERGLASS REPLACEMENT PARTS

CESSNA 182

What Makes These Composite Parts Such An Excellent Value?

- Stronger than factory originals with no weight increase.
- Easily repaired with locally available fiberglass kits if ever damaged.
- Exact replacements of original equipment means easy installation.
- Money back guarantee if not completely satisfied!

ELEVATORS & STABILIZERS



Here are some of our most popular items. These tips take a good deal of stress in just normal flying circumstances. They're also frequent victims of ramp rash. The original plastic simply can't stand up to the task as well as fiberglass replacements from Stene Aviation. Plus, if these parts ever do withstand damage, they're easily repaired with readily available fiberglass repair kits from your local automotive parts store.

Description	Part No.	Price
182 Elevator Tip 1965&on LH (SA-1234608-3)	05-03777	---
182 Elevator Tip 1965&on RH (SA-1234608-4)	05-03778	---
LH/RH 182 Horizontal Tip 1956-'59 (SA-0732613-1)	05-03779	---
LH/RH 182 Horizontal Tip 1965&on (SA-1232604-1)	05-03780	---
LH/RH 182 Horizontal Tip (SA-1232604-2)	05-12850	---
LH/RH 182 Horizontal Tip (SA-0732613-3)	05-12827	---

STRUT CUFFS



Here's an unbeatable item for renovating your Cessna; a set of replacement strut cuffs. Order just one cuff to replace a damaged original, or get a set of four for a complete replacement.

Description	Part No.	Price
182 Strut Cuff Upper RH (SA-0723605-4)	05-03774	---
182 Strut Cuff Upper LH (SA-0723605-3)	05-03773	---
182 Strut Cuff Lower 1962&on RH (SA-0723612-4)	05-03776	---
182 Strut Cuff Lower 1962&on LH (SA-0723612-3)	05-03775	---
LH 180 Strut Cuff Lower (SA-0723605-1)	05-03771	---
RH 180 Strut Cuff Lower (SA-0723605-2)	05-03772	---

RUDDER & VERTICAL FIN CAPS



These parts are a snap to replace on most planes. Please note, indicate if you have a straight tail or a swept tail. It is also important to let us know if your fin cap needs to accommodate a strobe or beacon, and if so, if the light is front-mounted or center-mounted.

Description	Part No.	Price
205/206/207/210 Vertical Fin (small beacon) 1964 - (SA-1231064-1)	05-03786	---
206/207 Vertical Fin (small beacon) 1967 - (SA-0731606-3)	05-03785	---
205/206/207/210 Rudder Top 1964 - (SA-0731606-9)	05-03793	---
206/207 Rudder Top 1967 - (SA-0731606-6)	05-03792	---
SA-1227402-3456SP	05-12846	---
SA-1227402-3456	05-12845	---
182 Rudder Top (SA-1231001-2)1976 & on	05-12847	---
182 Vertical Top (SA-1231059-1) 182P	05-12848	---
182 Vertical Fin (SA-1231064-10)182T, T182T	05-12849	---

182 TAILCONE

Replace your wore and cracked tailcone with a stronger than factory original fiberglass tailcone from Stene Aviation.
182 TailCone 1962&on (SA-1212010-15)
P/N 05-03794



GEAR LEG AND BRAKE FAIRINGS

These are excellent items for replacing worn plastic originals. Your fiberglass replacements will be more durable with an improved finish over the original plastics.

Description	Part No.	Price
182 Upper Gear Leg 1972-'75 RH (SA-1741005-200)	05-03799	---
182 Upper Gear Leg 1972-'75 LH (SA-1741005-201)	05-03801	---
182 Upper Gear Leg Fairing 1976&on RH (SA-1741052-200)	05-03802	---
182 Upper Gear Leg 1976&on LH (SA-1741052-201)	05-03803	---
182 Brake Fairing 1972-'74 RH (SA-0741634-18)	05-03806	---
182 Brake Fairing 1972-'74 LH (SA-0741634-19)	05-03807	---
182 Brake Fairing 1975-'78 RH (SA-0741634-10)	05-03808	---
182 Brake Fairing 1975-'78 LH (SA-0741634-11)	05-03809	---
182 Upper Gear Leg RH (SA-0741052-12)	05-12829	---
182 Upper Gear Leg LH (SA-0741052-11)	05-12828	---

WING & DORSAL TIPS



Wing tips are a common victim of hanger and ramp rash. Maybe you thought the plane was going to clear those doors as you wheeled it back into the hanger...the first indication that you were wrong was that grating sound as the wing tip met metal. Here's the solution: replacement fiberglass wing tips from Stene Aviation.

Description	Part No.	Price
182 Wing Tip (small droop) 1969-'72 LH (SA-0523565-29)	05-03726	---
182 Wing Tip (small droop) 1969-'72 RH (SA-0523565-30)	05-03727	---
182 Wing Tip (small droop) 1973&on LH (SA-0723200-5)	05-03762	---
182 Wing Tip (small droop) 1973&on RH (SA-0723200-6)	05-03764	---
182 Wing Tip (straight tip)- 1955-'67 (SA-0723615-200)	05-03797	---

WHEEL PANTS



Replace your original plastic wheel pants with high quality and durable fiberglass replacements. All wheel pants come with a 2" access plug for checking tire pressure. Original hardware is required for mounting.

Description	Part No.	Price
182 Wheel Pant 1975&on RH (SA-0541223-16)	05-03728	---
182 Wheel Pant 1975&on LH (SA-0541223-17)	05-03729	---
182 Nose Wheel Pant 1975&on (SA-0543079-3)	05-03730	---
180K/A185F LH Wheel Pant (SA-0741070-1)	05-12830	---
180K/A185F RH Wheel Pant (SA-0741070-2)	05-12831	---
182T/T182T LH Wheel Pant (SA-0741647-1)	05-12832	---
182T/T182T RH Wheel Pant (SA-0741647-2)	05-12833	---
182T/T182T Nose Wheel Pant (SA-0743050-14)	05-12834	---

SEE WWW.AIRCRAFTSPRUCE.COM FOR COMPLETE LISTING

WWW.AIRCRAFTSPRUCE.CA

Prices Subject to Change without Notice - Valid as of June 1, 2024.
Please view our website for current prices.

AP